



Product Change Notification



Product Group: Opto Modules & Visibles 17-JUL-2014 / PCN OMV-765-2014 Rev. 0

TITLE: Assembly Line Transfer PLCC2/3/4 and Mini SMD Package to New Location

DESCRIPTION OF CHANGE: The captive lines for PLCC2/3/4 and Mini LED assembly will be moved out of Nidec-Copal to ATEC. ATEC is a fully certified factory for automotive production, only 1 km away in the same industrial compound.
Equipment and process will be transferred without any change. The affected products will be re-qualified according to the high Vishay quality standards including AEC-Q101 criteria.
There will be no change to the products. Form, fit & function will be fully maintained.
With one exception:
VSML3710 and sub-types V3720PH, V3722PH, will undergo a chip replacement: The currently used 940nm T260V chip will be replaced by the 940nm TB9411VA chip. While the new chip will provide ~20% higher radiant intensity and faster switching times, the datasheet limits will not change. Affected customers for these devices will receive a separate detailed presentation (VSML3710_T260V to TB9411VA_140714.pdf).
For product qualification and customer samples assembly a pilot line was set up. This line will be integrated into the transferred lines afterwards.
Samples and PPAP are available on request.

CLASSIFICATION OF CHANGE: Assembly Site

REASON FOR CHANGE: Contract with Nidec-Copal is expired and not renewed
New chip for VSML3710 and sub-types V3720PH, V3722PH

EXPECTED INFLUENCE ON QUALITY RELIABILITY / PERFORMANCE: No influence on quality
No influence on reliability and performance

PRODUCT CATEGORY: LEDs

PART NUMBERS / SERIES / FAMILIES AFFECTED:

Please refer to attached detailed part number list

VISHAY BRAND(s): VISHAY SEMICONDUCTORS

TIME SCHEDULE:

Start Shipment Date: 22-OCT-2014

Last Time Buy Date:

Last Time Shipment Date:

SAMPLES AVAILABLE BEGINNING: 23-JUL-2014

We need samples for evaluation: Yes No
If Yes return this form to contact information below.

PRODUCT IDENTIFICATION: Label / date code

QUALIFICATION DATA: available upon request

Annotations about time schedule:

This PCN is considered approved, without further notification, unless we receive specific customer concerns before: 02-SEP-2014 or as specified by contract.

ISSUED BY:

PM: Franz Rettenmeier, Product Marketing Visibles

Phone: (+49) 7131 67-2276

Email: franz.retteneier@vishay.com

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

VISHAY Intertechnology Asia Pte. Ltd.
Regional Marketing Asia/Japan
25 Tampines Street 92
Keppel Building # 02-00
Singapore 528877
Phone: +65-6788-6668
Fax: +65-6788-3383

VISHAY Intertechnologies, Inc.
Regional Marketing The Americas - Opto
2201 Laurelwood Road
M/S 55
Santa Clara, CA 95014
USA
Phone: +1-408-567-8317
Fax: +1-408-567-8371

VISHAY Semiconductor GmbH
Regional Marketing Europe Opto
Theresienstr. 2
D-74025 Heilbronn
Germany
Phone: +49-7131-672976
Fax: +49-7131-673144



Product Change Notification



Product Group: Opto Modules & Visibles 17-JUL-2014 / PCN OMV-765-2014 Rev. 0

Attached Part Number List:

Visibles;;Visibles;;Visibles;;Visibles;;Visibles;;Visibles;;Visibles;;Visibles;;Visibles;;Visibles;;Visibles;;Visibles;;Visibles;;Sensors;;Sensors
 1.030.023.075;;8.925.510.226;;VLM2302-GS08;;VLSM20H2K1-GS08;;1427733;;8.925.406.028;;8.925.406.302;;8.928.510.330;;VLM31M2P1-
 GS18;;VLMK3100-GS08;;VLMO31J1K2-35-GS08;;VLMR33R2U2-GS08;;VLMW33T2U2-5K8L-18;;VLMY31J1K2-
 GS08;;V3700PH;;VEMT3700X01-GS18 1.030.023.155;;8.925.510.227;;VLM23N1P1-34-GS08;;VLSM20H2L1-
 GS08;;1427741;;8.925.406.039;;8.925.406.303;;8.928.510.331;;VLM3100-GS08;;VLMK3100-GS18;;VLMO31J1K2-GS08;;VLMR33R2U2-
 GS18;;VLMW33U2AA-5K8L-08;;VLMY31J1K2-GS18;;V3710PH-GS08;;VEMT3704F-GS08 436.045.021.00;;8.925.510.228;;VLM23N1P1-35-
 GS08;;VLSM20J2K2-GS08;;1428454;;8.925.406.040;;8.925.406.304;;8.928.510.354;;VLM3100-GS18;;VLMK3102-GS08;;VLMO31J1K2-
 GS18;;VLMR33T1U2-GS08;;VLMW33U2AA-5K8L-18;;VLMY31J1L2-GS08;;V3710PH-GS18;;VEMT3704FX01-GS08
 436.045.031.00;;8.928.510.039;;VLM23Q2S1-GS08;;VLSM20J2L1-GS08;;1428462;;8.925.406.042;;8.925.406.305;;8.928.510.355;;VLM3101-
 GS08;;VLMK3102-GS18;;VLMO31J1L2-GS08;;VLMR33T1U2-GS18;;VLMW33U2AA-6K7L-08;;VLMY31J1L2-GS18;;V3711PH-
 GS08;;VEMT3704FX01-GS18 436.045.041.00;;8.928.510.040;;VLM23Q2T1-GS08;;VLSM2100-
 GS08;;1432311;;8.925.406.043;;8.925.406.306;;8.928.510.356;;VLM3101-GS18;;VLMK3105-GS08;;VLMO31J1L2-GS18;;VLMRY3420-
 GS08;;VLMW41Q2R2-7K8L-P;;VLMY31J2K2-34-GS08;;V3711PH-GS18;;VEMT4700F-GS08 436.045.051.00;;8.928.510.041;;VLM23R2T1-
 GS08;;VLSM21H2K1-GS08;;1439561;;8.925.406.044;;8.925.406.315;;8.928.510.435;;VLM3105-GS08;;VLMK3105-GS18;;VLMO31K1L2-
 GS08;;VLMRY3420-GS18;;VLMW41Q2R2-8K8L-P;;VLMY31J2K2-GS08;;V3712PH;;VEMT4700-GS08 741121-70;;8.928.510.042;;VLMF2300-
 GS08;;VLSM21H2L1-GS08;;1439571;;8.925.406.045;;8.925.406.316;;8.928.510.436;;VLM3105-GS18;;VLMK3105-GS18;;VLMO31K1L2-
 GS18;;VLSM3000-GS08;;VLMW41Q2R2-P1P8-08;;VLMY31J2K2-GS18;;V3713PH-GS08;; 790438-70;;8.928.510.043;;VLMF23Q2S1-
 GS08;;VLSM21J2L1-GS08;;1439596;;8.925.406.069;;8.925.406.317;;8.928.510.437;;VLM3144-GS18;;VLMK31P1Q2-GS18;;VLMO333U2AB-
 GS08;;VLSM3000-GS18;;VLMW41Q2R2-P-GS18;;VLMY31K1L2-34-GS08;;V3713PH-GS18;; 790438-71;;8.928.510.044;;VLMF23Q2T1-
 GS08;;VLSM233T1V1-GS08;;1439601;;8.925.406.070;;8.925.406.318;;8.928.510.438;;VLM3145-GS18;;VLMK31P2S1-GS08;;VLMO333U2AB-
 GS18;;VLSM30G2J1-GS18;;VLMW41R1T1-5K8L-08;;VLMY31K1L2-GS08;;V3714PH-GS08;; 8.925.405.497;;8.928.510.119;;VLMF23R2T1-
 GS08;;VLSM234V2BA-GS08;;436.034.121.00;;8.925.406.071;;8.925.406.329;;8.928.510.439;;VLM31N2Q1-34-GS18;;VLMK31P2S1-
 GS18;;VLMO33R2U2-GS08;;VLSM30J1K2-GS08;;VLMW41R1T1-5K8L-18;;VLMY31K1L2-GS18;;V3714PH-GS18;;
 8.925.405.498;;8.928.510.120;;VLMF23S1T1-35H-08;;VLMY2000-
 GS08;;436.034.131.00;;8.925.406.072;;8.925.406.333;;8.928.510.440;;VLM31Q1R2-34-GS08;;VLMK31Q1R2-GS08;;VLMO33R2U2-
 GS18;;VLSM30J1K2-GS18;;VLMW41R1T1-7K8L-08;;VLMY333V2AB-46-18;;V3720PH-GS08;; 8.925.406.005;;8.928.510.121;;VLMG21J2L1-
 GS08;;VLMY20J1L2-GS08;;436.034.141.00;;8.925.406.073;;8.925.406.334;;8.928.510.441;;VLM31Q2T1-35-GS08;;VLMK31Q1R2-
 GS18;;VLMO33S1T2-GS08;;VLSM30J1L2-GS08;;VLMW41S1T1-5K8L-08;;VLMY333U1AA-GS08;;V3722PH;;
 8.925.406.006;;8.928.510.122;;VLMG21J2M1-GS08;;VLMY20K1L2-34-
 GS08;;54.141.025;;8.925.406.074;;8.925.406.335;;8.928.510.442;;VLM31Q2T1-35-GS18;;VLMK31R1S1-GS08;;VLMO33S1T2-
 GS18;;VLSM30J1L2-GS18;;VLMW41S1T1-5K8L-18;;VLMY333U1AA-GS18;;V3780PH-GS18;; 8.925.406.007;;8.928.510.212;;VLMG21K1L2-
 GS08;;VLMY20K1L2-GS08;;54.141.049;;8.925.406.075;;8.925.406.336;;8.928.510.541;;VLM31Q2T1-GS08;;VLMK31R1S1-
 GS18;;VLMO33T1U2-GS08;;VLSM30J2K2-GS08;;VLMW41S1T1-8K8L-08;;VLMY333U2V1-B-GS08;;V3790PH-GS08;;
 8.925.406.008;;8.928.510.213;;VLMG21K2M1-GS08;;VLMY2100-
 GS08;;6.033.EC2.109;;8.925.406.076;;8.925.406.352;;8.928.510.542;;VLM31Q2T1-GS18;;VLMK31R1S2-GS08;;VLMO33T1U2-
 GS18;;VLSM30J2K2-GS18;;VLMW41S1T2-5K5L-08;;VLMY334BACB-GS08;;V3790PH-GS18;; 8.925.406.031;;8.928.510.214;;VLMK2000-
 GS08;;VLMY21H2K1-GS08;;6.033.EC2.143;;8.925.406.101;;8.925.406.353;;8.928.510.543;;VLM31R1S2-GS08;;VLMK31R1S2-
 GS18;;VLM3100-GS08;;VLSM30K1L2-GS08;;VLMW41S1T2-5K6L-08;;VLMY334BACB-GS18;;V3940PHX01-GS08;;
 8.925.406.032;;8.928.510.215;;VLMK2001-GS08;;VLMY21H2L1-GS08;;6.033.EC2.194;;8.925.406.102;;8.925.406.354;;VLM3100-
 GS08;;VLM31R1S2-GS18;;VLMK31R2S2-GS08;;VLM3100-GS18;;VLSM30K1L2-GS18;;VLMW41S1T2-6K6L-08;;VLMY33R2U2-
 GS08;;V3940PHX01-GS18;; 8.925.406.033;;8.928.510.225;;VLMK20J2L1-GS08;;VLMY21J2L1-
 GS08;;6.033.EC2.195;;8.925.406.116;;8.925.406.361;;VLM3100-GS18;;VLM31S1T1-GS08;;VLMK31R2S2-GS18;;VLM3101-
 GS08;;VLSM30K2L2-GS08;;VLMW41S1T2-6K7L-08;;VLMY33R2U2-GS18;;VSM3940X01-GS08;;
 8.925.406.034;;8.928.510.226;;VLMK20J2L2-GS08;;VLMY233T2V2-GS08;;6.033.EC2.331;;8.925.406.141;;8.925.406.362;;VLM3000L-
 GS08;;VLM31S1T1-GS18;;VLMK333U2AB-GS08;;VLM3101-GS18;;VLSM3100-GS08;;VLMW41S1T2-7K8L-08;;VLMY33T1U2-
 GS08;;VSM3940X01-GS18;; 8.925.406.035;;8.928.510.227;;VLMK20K1L2-GS08;;VLMY233V1V2-56-
 08;;6.033.EC2.332;;8.925.406.142;;8.925.406.363;;VLM31J2K2-3-GS18;;VLMF3100-GS08;;VLMK333U2AB-GS18;;VLM3102-
 GS08;;VLSM3100-GS18;;VLMW41S1T2-8K8L-08;;VLMY33T1U2-GS18;;VSM3942X01-GS08;; 8.925.406.036;;8.928.510.228;;VLMK2300-
 GS08;;VLMY234ABCA-GS08;;6.033.EC2.334;;8.925.406.143;;8.925.406.364;;VLM3100-GS18;;VLMK334BACB-
 GS08;;VLM3102-GS18;;VLSM3101-GS08;;VLMW41S1T2-JKLL-08;;VLMY33T2U2-46-GS08;;VSM3943X01-GS08;;
 8.925.406.054;;8.928.510.270;;VLMK233U1AA-GS08;;1.030.006.039;;6.033.EDO.086;;8.925.406.144;;8.925.406.415;;VLM31J2K2-
 GS18;;VLMF3107MM-GS18;;VLMK334BACB-GS18;;VLM3107-GS08;;VLSM3101-GS18;;VLMW41S1T2-JKPL-08;;VLMY30G2J1-
 GS08;;VSM3943X01-GS18;; 8.925.406.055;;8.928.510.271;;VLMK233U1V1-34H-
 08;;1.030.006.040;;6.033.EDO.087;;8.925.406.145;;8.925.406.416;;VLM31J2L2-GS08;;VLMF31Q2T1-GS08;;VLMK33Q2T1-GS08;;VLM3107-
 GS18;;VLSM31J1K2-GS08;;VLMW41S1T2-JKPL-18;;VLMY30G2J1-GS18;;VSMF3700-GS08;;
 8.925.406.056;;8.928.510.272;;VLMK234ABCA-GS08;;1.030.023.000;;6.033.EDO.088;;8.925.406.154;;8.925.406.417;;VLM31J2L2-
 GS18;;VLMF31Q2T1-GS18;;VLMK33Q2T1-GS18;;VLM31G2J1-GS08;;VLSM31J1K2-GS18;;VLMW41S1T2-KKLL-08;;VLMY30G2K1-
 GS08;;VSMF3710-GS08;; 8.925.406.057;;8.928.510.332;;VLMK23P2R1-GS08;;1.030.023.002;;727893-
 68;;8.925.406.249;;8.925.406.418;;VLM31K1L2-3-GS18;;VLMF31R1S2-35-GS08;;VLMK33R1S2-GS08;;VLM31G2J1-GS18;;VLSM31J1L2-
 GS08;;VLMW41S1T2-LKML-08;;VLMY30G2K1-GS18;;VSMF3710-GS18;; 8.925.406.062;;8.928.510.333;;VLMK23P2S1-
 GS08;;1.030.023.006;;727893-69;;8.925.406.250;;8.928.510.110;;VLM31K1M1-3-GS18;;VLMF31R1S2-35-GS18;;VLMK33R1S2-
 GS18;;VLM31G2J2-GS08;;VLSM31J1L2-GS18;;VLMW41S1T2-LKML-18;;VLMY30H2K1-GS08;;VSMF4710-GS08;;
 8.925.406.063;;8.928.510.334;;VLMK23Q2S1-GS08;;1.030.023.073;;727893-72;;8.925.406.251;;8.928.510.172;;VLM31K2L2-3-
 GS18;;VLMF31R1S2-GS08;;VLMK33R2T2-2-GS08;;VLM31G2J2-GS18;;VLSM31J2L1-GS08;;VLMW41S1T2-MKLN-08;;VLMY30H2K1-
 GS18;;VSMF4720-GS08;; 8.925.406.064;;8.928.510.367;;VLMK23R1S1-GS08;;1.030.023.074;;727893-
 80;;8.925.406.252;;8.928.510.173;;VLM31K2L2-GS08;;VLMF31R1S2-GS18;;VLMK33S1T1-2-GS08;;VLM31H2J2-GS08;;VLSM31J2L1-
 GS18;;VLMW41S1T2-NKOL-08;;VLMY33P1Q2-GS08;;VSMF9700X01-GS08;; 8.925.406.065;;8.928.510.368;;VLMO2000-
 GS08;;1.030.023.076;;727893-81;;8.925.406.253;;8.928.510.198;;VLM31K2L2-GS18;;VLMF31R2S2-34K-08;;VLMK33S1T1-
 GS08;;VLM31H2J2-GS18;;VLSM31K1L2-GS08;;VLMW41S1T2-OKPL-08;;VSMF9700X01-GS18;;
 8.925.406.078;;8.928.510.369;;VLMO20J2M1-GS08;;1.030.023.077;;736267-71;;8.925.406.254;;8.928.510.199;;VLM3040L1M2-34-
 GS08;;VLMF31S1T1-GS08;;VLMK33S1T1-GS18;;VLM30E1F2-GS08;;VLSM31K1L2-GS18;;VLMW42T2U2-6K6L-08;;VSMG2700-GS08;;

8.925.406.079;;8.928.510.370;;VLMO20K1L2-34-GS08;;1.030.023.078;;736267-72;;8.925.406.265;;8.928.510.200;;VLMB41P1Q2-GS08;;VLMF31S1T1-GS18;;VLMKE3400-GS08;;VLMPG30E1F2-GS18;;VLMS333T2V2-GS08;;VLMW42T2V1-6K7L-08;;VSMG2700-GS18;;8.925.406.080;;8.928.510.371;;VLMO20K2L2-35-GS08;;1.030.023.080;;736418-70;;8.925.406.266;;8.928.510.201;;VLMB41P1Q2-GS18;;VLMG3100-GS08;;VLMKE3400-GS18;;VLMPG30E1G2-GS08;;VLMS333T2V2-GS18;;VLMW45Q2R2-8K-08;;VSMG2720-GS08;;8.925.406.167;;8.928.510.372;;VLMO20K2M1-34-GS08;;1.030.023.124;;790639-70;;8.925.406.267;;8.928.510.202;;VLMB41P2Q2-GS08;;VLMG3100-GS18;;VLMKE3401-GS08;;VLMPG30E1G2-GS18;;VLMS334AABB-GS08;;VLMW45Q2R2-8K8L-08;;VSMG3700-GS08;;8.925.406.168;;8.928.510.373;;VLMO2100-GS08;;1.030.023.129;;8.909.001.029;;8.925.406.268;;8.928.510.209;;VLMB41P2Q2-GS18;;VLMG3102-GS08;;VLMKE3401-GS18;;VLMPG30F1G2-GS08;;VLMS334AABB-GS18;;VLMW45R1S1-5K6L-08;;VSML3710-GS08;;8.925.406.169;;8.928.510.387;;VLMO21H2K1-GS08;;1.030.023.276;;8.925.405.160;;8.925.406.269;;8.928.510.210;;VLMC3100-GS08;;VLMG3102-GS18;;VLMKG3400-GS08;;VLMPG30F1G2-GS18;;VLMS33S1T2-GS08;;VLMW45R1S2-H1H2-08;;VSML3710-GS18;;8.925.406.178;;8.928.510.388;;VLMO21H2L1-GS08;;1.030.023.277;;8.925.405.161;;8.925.406.270;;8.928.510.211;;VLMC3100-GS18;;VLMG3105-GS08;;VLMKG3400-GS18;;VLMPG31L1M2-GS08;;VLMS33S1T2-GS18;;VLMY3000-GS08;;VSMG3700-GS08;;8.925.406.179;;8.928.510.389;;VLMO21J2L1-GS08;;1.030.023.402;;8.925.405.162;;8.925.406.275;;8.928.510.218;;VLMC3101-GS08;;VLMG3105-GS18;;VLMO3000-GS08;;VLMPG31L1M2-GS18;;VLMS33S1U1-GS08;;VLMY3000-GS18;;VSMG3700-GS18;;8.925.406.180;;8.928.510.390;;VLMO233U1AA-GS08;;1.030.023.660;;8.925.405.220;;8.925.406.276;;8.928.510.250;;VLMC3101-GS18;;VLMG31K1L2-GS08;;VLMO3000-GS18;;VLMPG3301-GS18;;VLMS33S1U1-GS18;;VLMY30J2L1-GS08;;VSMY3850-GS08;;8.925.406.244;;8.928.510.395;;VLMO233U2V2-35-08;;1.030.023.661;;8.925.405.221;;8.925.406.277;;8.928.510.251;;VLMG3100-GS08;;VLMG31K1L2-GS18;;VLMO30K1L2-GS08;;VLMPG33N1P2-GS08;;VLMT3100-GS08;;VLMY30J2L1-GS18;;VSMY3850-GS18;;8.925.406.245;;8.928.510.396;;VLMO20D2G1-GS08;;1.030.023.850;;8.925.405.222;;8.925.406.287;;8.928.510.252;;VLMG3100-GS18;;VLMG31K1M2-GS08;;VLMO30K1L2-GS18;;VLMPG33N1P2-GS18;;VLMT3100-GS18;;VLMY30J2M1-GS08;;VSMY3940X01-GS08;;8.925.406.278;;8.928.510.397;;VLMO232M2N2-GS08;;1.030.023.851;;8.925.405.433;;8.925.406.288;;8.928.510.253;;VLMG3101-GS08;;VLMG31K1M2-GS18;;VLMO30K1M2-GS08;;VLMR31Q2T1-GS08;;VLMTG41S2U1-GS08;;VLMY30J2M1-GS18;;VSMY3940X01-GS18;;8.925.406.279;;8.928.510.432;;VLMO232M2N2-O-GS08;;1375822;;8.925.405.435;;8.925.406.289;;8.928.510.313;;VLMG3101-GS18;;VLMG31L1M2-GS08;;VLMO30K1M2-GS18;;VLMR31Q2T1-GS18;;VLMTG41S2U1-GS18;;VLMY30K2M1-GS08;;E3713PH-GS08;;8.925.406.280;;8.928.510.433;;VLMO232M2P1-GS08;;1375830;;8.925.405.446;;8.925.406.290;;8.928.510.314;;VLMG3105-GS08;;VLMG31L1M2-GS18;;VLMO30K2M1-34K-08;;VLMR31R2T1-34-GS08;;VLMV3100-GS08;;VLMY30K2M1-GS18;;E3713PH-GS18;;8.925.406.281;;8.928.510.434;;VLMO232N1P1-GS08;;1375849;;8.925.405.474;;8.925.406.291;;8.928.510.315;;VLMG3105-GS18;;VLMH3100-GS08;;VLMO30L1M2-GS08;;VLMR31R2T1-34-GS18;;VLMV3100-GS18;;VLMY3100-GS08;;E3722PH;;8.925.406.386;;8.928.510.618;;VLMO232K2M2-GS08;;1375857;;8.925.405.485;;8.925.406.292;;8.928.510.319;;VLMG31L2N1-GS08;;VLMH3100-GS18;;VLMO30L1M2-GS18;;VLMR333U1AA-GS08;;VLMW33S2V1-5K8L-08;;VLMY3100-GS18;;VEMT3700F-GS08;;8.925.406.387;;8.928.510.619;;VLMO232L2M2-GS08;;1375865;;8.925.405.486;;8.925.406.293;;8.928.510.320;;VLMG31L2N1-GS18;;VLMH3101-GS08;;VLMO3100-GS08;;VLMR333U1AA-GS18;;VLMW33S2V1-5K8L-18;;VLMY3101-GS08;;VEMT3700FX01-GS08;;8.925.406.388;;8.928.510.620;;VLMR233T2V2-GS08;;1375873;;8.925.406.025;;8.925.406.299;;8.928.510.321;;VLMG31L2P1-GS08;;VLMH3101-GS18;;VLMO3100-GS18;;VLMR333U1AA-M-GS18;;VLMW33T2AA-5K8L-08;;VLMY3101-GS18;;VEMT3700FX01-GS18;;8.925.406.389;;VLMB21K2L2-3-GS08;;VLMR234ABCA-GS08;;1375881;;8.925.406.026;;8.925.406.300;;8.928.510.322;;VLMG31L2P1-GS18;;VLMH3102-GS08;;VLMO3101-GS08;;VLMR334BACB-GS08;;VLMW33T2AA-5K8L-18;;VLMY3102-GS08;;VEMT3700-GS08;;8.925.510.225;;VLMO2300-GS08;;VLMS2000-GS08;;1375891;;8.925.406.027;;8.925.406.301;;8.928.510.329;;VLMG31M2P1-GS08;;VLMH3102-GS18;;VLMO3101-GS18;;VLMR334BACB-GS18;;VLMW33T2U2-5K8L-08;;VLMY3102-GS18;;VEMT3700X01-GS08;;